

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,812,905 B2
DATED : November 2, 2004
INVENTOR(S) : Thomas et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1.

Line 52, reads "...around ten wafts." and should read -- ...around ten watts. --.


Column 6.

Line 28, reads "...support structure, end an antenna..." and should read -- ...support structure, and an antenna... --.

Line 62, reads "...between said the first RF transceiver and..." and should read -- ...between the said first RF transceiver... --.

Signed and Sealed this

Nineteenth Day of April, 2005



JON W. DUDAS
Director of the United States Patent and Trademark Office